

Vulnerability Assessment – Rapid Visual Screening

Major (Dr) C S Sanghvi

Professor

APPLIED MECHANICS DEPARTMENT

L D COLLEGE OF ENGINEERING

AHMEDABAD – 380 015

LEVELS OF EVALUATION

LEVEL-1

Rapid Visual Screening (RVS)

LEVEL-2

Simplified Vulnerability Assessment (SVA)

LEVEL-3

Detailed Vulnerability Assessment (DVA)

Rapid Visual Screening (RVS) Procedure


- **For mass scale screening of existing buildings**
- **Limited to visual inspection and identification of potential seismic defects/deficiencies**
- **Use of checklists**
- **For post-earthquake vulnerability survey**

Simplified Vulnerability Assessment (SVA) Procedure

- For buildings identified during Rapid Visual Screening
- More detailed visual survey, preliminary measurements and study of available design documents, drawings and repair documents, if any.
- Simplified calculation for forces in members

Detailed Vulnerability Assessment (DVA) Procedure

- **For vulnerability of assessment of individual buildings**
- **Detailed in-situ investigation of material strength, defects and deterioration**
- **Detailed analysis**



SOURCES OF DEFICIENCIES

Defects in the original design

- 1. Under estimation of loads**
- 2. Old standards**
- 3. Improper detailing**

SOURCES OF DEFICIENCIES

Defects during construction

- 1. Under strength concrete**
- 2. Poor compaction**
- 3. Poor construction joints**
- 4. Improper placing of reinforcement**
- 5. Honey-combing**

SOURCES OF DEFICIENCIES

Deterioration due to improper maintenance

- 1. Reinforcement corrosion**
- 2. Alkali-aggregate reaction**

VISUAL INSPECTION AND STUDY OF BUILDING CONFIGURATION

- 1. Asymmetry of configuration**
- 2. Irregularity in stiffness**
- 3. Location of shear wall, stair case, service core**
- 4. Location and condition of separation joints**
- 5. Distress shown by structure, e.g cracks, spalling**
- 6. Year of construction and IS Codes followed**
- 7. Seismic zone**
- 8. Extension and past repairs**

SOFT FIRST STOREY




DAMAGE TO SOFT FIRST STOREY BUILDING DURING EARTHQUAKE



DISSIMILAR ADJACENT BUILDING



HEAVY MASS AT TOP



STIFFNESS AND PLAN IRREGULARITY



BEAM COLUMN OFFSET



NON-FUNCTIONAL SEPARATION JOINT



MONOLITHIC STAIRCASE




SHORT COLUMN EFFECT



STUDY OF DRAWINGS

- 1. Symmetry and grid pattern**
- 2. Ductile detailing and confining reinforcement**
- 3. Anchorage of beam reinforcement into column**
- 4. Splicing of reinforcement**
- 5. Anchorage of shear wall reinforcement in to beam, slab and column**
- 6. Confining reinforcement in shear walls**

LACK OF SHEAR REINFORCEMENT



LACK OF CONFINING




LACK OF ANCHORAGE



IMPROPER SPLICING




IN-SITU EVALUATION TOOLS




REBOUND HAMMER

SURFACE HARDNESS TEST




IN-SITU EVALUATION TOOLS




USPV TESTER


PENETRATION RESISTANCE TEST




PENETRATION RESISTANCE TEST




PULL OUT TEST



PULL OUT TEST




IN-SITU EVALUATION TOOLS




PULL-OUT TEST

PULL-OFF TEST



PULL-OFF TEST



Thank You